

The class is subject to the auxiliary blast air receiver ~~not~~ being used.

2 E

Chief Engineer Surveyor

Received from Chief Engineer Surveyor

NAME "JEAN MARIE"

REPORT

Ant. **30 JUN 1955** No. 30253

Remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/6/52.)

Survey COMPLETION OF SPECIAL SURVEY OF ~~ENGINES AND~~ BOILERS

This Survey, due 3,55 <sup>now</sup> ~~partly~~ held

~~now~~

~~completed, and the following repairs carried out (due to~~

):-



© 2021



It is submitted the vessel is eligible to remain as classed, with notation of DBS 6,55 subject as above. ~~to be recommended.~~

Lloyd's Register Foundation

010229-010235-0108

29.6.55