

to Chief Surveyors

Received from Chief Surveyors

1726 NOV 8

VESSEL'S NAME Stl. So. "HUMANITAS".

Report Lon.

No. 91601a.

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/6/92.)

2nd No. 3

SURVEY PARTLY HELD.

When due

5.76

When proposed to be completed

Portion of Survey held, &c.,


The 2nd S.S.No.3, due 5,26, has been partly held by the examination of the upper and lower tween deck bunkers amidships and of the aftermost double bottom tank.

Some repairs are required in the bunkers and to ventilators in the tween decks, some indented bow plating requires to be faired and the rudder to be rebushed.

A proposal to complete the survey on the vessel's return from her contemplated voyage in 2 months was agreed to on the 8th February last.

The Marseilles Surveyors recently stated the vessel was being cleaned and repaired at that port under the survey of the Registro Italiano Non-exclusive Surveyor, but the Society's Surveyors had not been called in and it was concluded the Owner did not intend to continue the class.

The Genoa Surveyors in reply to enquiry now forward a letter from the Owners who state that owing to the present age of the vessel, the necessity of classing her with the Registro Italiano and for general reasons of economy, they have decided not to



© 2021

Lloyd's Register
Foundation


010276-010282-0163 P.T.O.

Stl.Sc."HUMANITAS". 2.



maintain the classification of this Society.

The year of grace expired 5,27.

It is submitted the class of the vessel be
expunged from the Register Book with a Red Line (8.27),
indicating non-compliance with the Society's Rules.




5. 8. 27.


© 2021

Lloyd's Register
Foundation

0163 2/2