

COPY.

15th January, 1919.

Dear Salmon,

re S.S. "ANGLO SAXON"

With reference to the Secretary's letter of the 1st instant re the circulating pipes fitted in the Donkey Boiler of this vessel, I am forwarding you a portion of one of these pipes which have now been cut out of this Boiler.

The Hull Surveyors state they are informed by the Chief Engineer that this Boiler has only been working six weeks since the circulating pipes were fitted, about half this time being under banked first. ?

I think this case should, if possible, be brought to the notice of the Firm who fitted these circulating pipes as with salt water feed they are a positive danger.

Yours sincerely,

(Signed) H.P.K.

F.M. Salmon, Esq.,

NEW YORK.



© 2021

Lloyd's Register
Foundation

010776-010782-0109