

S.S. "ANGLO SAXON".

The Hull Surveyors forward a sketch of a circulating arrangement which has been fitted in the Donkey Boiler of this Vessel, apparently at New York. They state that the Owners desire to know whether the Committee approve of this arrangement.

It is submitted the Hull Surveyors should be informed that there is no report in this Office of any circulating pipes being fitted in the Donkey Boiler of this Vessel.

In view of the Boiler being fed with salt water and the impossibility of cleaning or internally examining the pipes in question, it is considered they are a source of danger and approval cannot be given to the same. They should advise the Owners Superintendent accordingly and arrange for these pipes to be removed.

The New York Surveyors should be advised of the above and a copy of the sketch forwarded should be sent to them for their information.

ARK
4.1.19.

17



© 2021

Lloyd's Register
Foundation

010276-010282-0196

Sections (if chargeable).....

Received by me,

6.1.19

RBH

John V. Pol...