

1m, 12, 12.

7

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME *Stl S. POLYTHIA*

Rpt. *Off*

No. *45486*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

DAMAGE AND PART *1st* S.S. No. *2*

Damage through *grounding*  
*because not stated*  
now repaired as follows:-

	Plates	Frames	R.Frames	Floors	Beams	Str.	Plates	Dk.	Plates
Renewed .....									
Removed and faired or repaired.....									
Faired or repaired in place.....									

Other items:-

*Vessel placed in drydock; bottoms coated.  
The Surveyor recommends that if slightly indented  
shell plating be dealt with at the Owners convenience*

The *1st* S.S. No. *2* due *2. 15* has also been partly held and the  
*to complete same the following remains:- Ceiling to left  
following repairs done due to wear and tear:- all 1st tanks & weak tanks  
to test, forecsts, plating under side lights, a 15 pipes.  
mask, rigging & steering gear to examine.*

~~It is proposed to complete the survey~~

*A proposal to hold the special  
survey during the year of grace  
was agreed to in March last*

It is submitted ~~this proposal might be approved and~~ the vessel be  
allowed to remain as classed, — record of Survey, and notation of  
S.S. No. *2* being deferred until completion of same.

The following remains to be done to complete the *1st* S.S. No. *2*

viz:- *As above*

*Indented plating on starboard side to be dealt with  
at Owners convenience.*



© 2021

Lloyd's Register  
Foundation

010283-010288-0021

FEB 10 AUG 1921

TUES. 21 SEP 1926

TUES. 30 NOV 1926

DEC 10 1926

(The Sur

Character Assigned

*Deferred for  
comp. No. 2*

med) as }  
verified }  
Salvage  
through  
Survey.  
rated

cleaned  
Peak  
Hatch  
examined

beiling  
aminat

king pin

M. of Wood Ves  
(on Felt.)  
on, Month

ow ascertained  
wedges removed

letter  
of 38

te if now range  
board) 21  
length 21

Warps  
Running Rigging

register Book con  
lassed and to h

our op  
He no  
shell

Register of Sh

23 OCT 1926