

Received from Chief Ship Surveyor 20 JUL 1959

SHIP'S NAME "FUKUZAN MARU"

REPORT

Smk.

No. 71

GB

Outstanding Conditions of Class: NONE.

S.R.L. — Appendix. (As before ~~or None~~)

Nature of Present Survey: ~~(at float and~~ in dry dock)

Permanent repairs to damages from various causes:  
Permanent/deferred repairs to wasted bulkhead and 'tween deck plating.

Recommendation:

SUBMITTED record of 'DS 6,59' be assigned as recommended, subject to Nos. 1/2 and 2/3 hold bulkheads and 'tween deck plating being permanently repaired at the Special Survey.

DS 6,59. Subject.

S.R.L. APPENDIX NOTE (AMENDED).  
Indented D.B. tank top  
and tunnel plating.



© 2021

Lloyd's Register  
Foundation