


ATAGO MARU

KOB 895-

NO 52176 IN RB

Before this case receives consideration
IT IS SUBMITTED the surveyors be requested
to state whether the steam pipes have
been tested as required by the Rules

Yes



© 2021

Lloyd's Register
Foundation

010294-010299-0123