

COPY.

Lloyd's Register of Shipping,

71, Fenchurch Street, E.C. 3.

14th February, 1925.

Dear Sirs,

M. With reference to your First Entry Report No.29014 on the S.S."QUERIMBA", I have to inform you it is concluded that the inner surface of the bottom plating in way of the dry tank under boilers is protected with cement, but I shall be glad if you will be good enough to state if this is so.

I am, Dear Sirs,

Yours faithfully,

Secretary.

The Surveyors,

SUNDERLAND.



© 2021

Lloyd's Register
Foundation

010294-010299-0187