

LONDON.

COPY

# LLOYD'S REGISTER OF SHIPPING



Port MARSHILLE

27th September 1962.

13.462

This is to Certify that I have surveyed part of the machinery  
of the MV DEBORAH 11.963 Gross tons of Monrovia

for purpose of completion of Continuous Survey of Engines, completion  
of Steam Pipe Survey, Auxiliary Boiler Survey and Tail Shaft Survey.

and that all my recommendations have been carried out to my satisfaction. I  
am reporting accordingly and recommending to the Committee of Lloyd's Register  
of Shipping that the machinery classification should be retained and the following  
survey records assigned

CSM 9.62 (now) S.P.S. 9.62 (now) ABS 9.62 (now) and TS.CL 4.62 (now)  
subject to the repairs (METALOCK) to the main engine Nos 2 & 3 cylinder  
blocks being re-examined by 12-63 but without condition of class in  
respect of the propeller and sea connections.

## Parts now examined:—

CS All pumps in pump room viz :- Port & Starbd ballast pumps, Port &  
Starbd bilge pumps, Emergency fire pump.  
Sea connections.

S.P.S. Deck steam pipe serving ballast pumps & windlass tested.

ABS Port & Starbd auxiliary boilers examined.  
Exhaust gas economiser examined.

T.S.CL. Tail shaft examined

Propeller & external fastenings examined.

*N. A. Dawson*

N. A. DAWSON

Surveyor to Lloyd's Register of Shipping

## KEY TO ABBREVIATIONS

ABS Auxiliary Boiler Survey  
CSM Continuous Survey of Machinery  
DBS Donkey Boiler Survey  
ES Engine Special Survey

MBS  
OF  
SGS  
SPS

Main Boiler Survey  
Fitted for oil fuel (date) FP above 150° F.  
Steam Generator Survey  
Steampipe Survey

TS Tailshaft Survey  
TS(CL) Tailshaft Survey—Continuous Liner  
TSN Tailshaft renewed  
TS(OG) Tailshaft Survey—Oil Gland

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—  
"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

Cert. B.1. 120m,4,62 (MADE AND PRINTED IN ENGLAND.)

Lloyd's Register  
Foundation

010 300-010308-0030