

Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules and items remaining to complete the Surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be reported in detail.

3m,10.52

11 FEB 1953

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

SHIP'S NAME "CALIFORNIA MARU"

REPORT

Kob. No. 979

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

(The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement.—Extract from Sub-Committee's Report. 24/5/32.)

The class of this ship #100A1 "Carrying Petroleum in Bulk" was withdrawn from the Register Book in 11,48 and three dots (...) inserted in lieu indicating withdrawal at Owners' request.

Reclassification with the Society is now desired.

The KOBE Surveyors report (8,52), the ship placed in dry dock and the requirements of a SPECIAL SURVEY (C) for Reclassification complied with.

Due to damage sustained during hostilities, extensive repairs have been effected to shell and deck plating (p & s), cargo oil and fuel oil tanks and other items.

Concurrently with the above the length of the ship has been increased by 19'9" in accordance with approved arrangements.

IT IS SUBMITTED the ship is eligible to have her class #100A1 "Carrying Petroleum in Bulk" reinstated in the Register Book with particulars as formerly, and to have record of docking 7,52 and Notation of 'ss.Osk. 8,52' assigned as recommended, subject to the sternframe (E.W.7,52) being specially examined at the next drydocking.

REINSTATE CLASS IN R.B.

#100A1 "Carrying Petroleum in Bulk"
7,52 Osk.
ss.Osk. 8,52.
Reclassed 8,52.
Particulars as formerly.

|| P.T.O. ||

AMEND R.B. to -

13BH

F 77'

"gt"

OL 545.3'

INSERT IN R.B.

Len. 8,52.



© 2021

Lloyd's Register Foundation

010309-010316-0096 1/2

0096 4/2

Handwritten signature and date: J.B.M. 3.2.52

- 2 -

"CALIFORNIA MARU"

IT IS FURTHER SUBMITTED, in the absence of approved plans the Surveyors be requested to confirm that the "As Fitted" plans are also "As Approved", and in future similar cases this should be so indicated and initialled on the plans.

They should be informed -

(1) it is concluded the alterations effected at this time have been carried out in accordance with the approved plans and the Society's letters,

(2) that the anchor and chain cable equipment was verified with certificates, and

be requested to forward the weights of the 1st & 2nd bower anchors also the new overall length.

[Handwritten signature]
5-2-53



© 2021

Lloyd's Register Foundation

0096 2/2

ssifi
board (S
Ship an
if so, b
3.
and
nes,
of s
and
gener
stri
tar
es. O
Cop
Wh
Boa
Ma
Cor
Equ
An
Cal
Ch
Ha
Sta
Sa
ication
ut fra
of ss
our
tat
fra