

Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

AME ENDERBYREPORT NwcNo. 115777

4E

21 JAN 1959

This is a CS case, and it is noted that many items of main and auxiliary machinery are reported as completely overhauled yet do not appear in the report as having been examined; e.g.: main thrust bearing, intermediate shafting, condensers, various pumps, etc. Consequently, before this report can be considered, Newcastle Surveyors are asked to state which items of machinery can be credited towards the CS and issue a fresh Interim Certificate B1 if necessary.



20 JAN 1959

4² Siggers to note.

Inst. 301/159



© 2021

Lloyd's Register
Foundation

010338-010354-0240