

COPY.

Lloyd's Register of Shipping,

71, Fenchurch Street, E.C. 3.

9th August, 1926.

Dear Sirs,

With reference to your report No. 5088 on the steamer "MALAY MARU", I shall be glad to learn what arrangements the Owners propose making for the 2nd special survey No. 2 to be completed.

I should add that in May last the Society's Surveyor at Singapore reported the vessel had sustained damage to shellplating on the starboard side through collision, and the vessel's class has been allowed to remain undisturbed subject to repairs being effected at the Owners' convenience.


I am, Dear Sirs,

Yours faithfully,

Clerk to the Classification
Committee.

The Surveyors,

KOBE.



© 2020

Lloyd's Register
Foundation

010391-010409-0043