

(3,000,49.)

Received by Chief Ship Surveyor 21/7/09

Received from Chief Ship Surveyor _____

VESSEL'S NAME Stt SD No 73' Rpt. Rot No. 6190

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

Nature of Survey First entry

It is submitted that before this case reaches the consideration of the Committee the Newcastle Surveyor should be informed that the vessel has proceeded to ~~the~~ South Shields where her machinery is to be fitted by Messrs G J Guyble, and in order to complete the Survey for Classification the following repairs to be done:- the top of the engine & boiler casing & the engine room skylight to be riveted, & the tunnel top, with stiffeners & one stiffener on the coal shoot bulkhead to be riveted. They should be requested to give the case the necessary attention & on completion of the work to forward a report on form 8. with a view to the Classification of the vessel.

Lt. NWC 21/7/09.

J.P.B. W.C. 2010
21/7/09
Lloyd's Register Foundation
610391-010404-0131