

REPORT OF TOTAL LOSS, CASUALTY, &c.

9607

21685 in R. B. Wreck Book, p. 19/39 Date of writing this report 1st August, 1939.
 Vessel's Name Steel Twin S.S. "Camprodon" of Barcelona Tons {Gross 1024
 Net 447
 Built at Santander When 1934 5 Casualty notice sent to Owner Owner's reply
 Owner's Name Compañia Arrendataria del Monopolio de Petroleos S.A.
 Address Apartado 518, Torija 9, Madrid, Spain

Case previously before Date
 Classing Committee. Last Minute
 Particulars of Classification.
 1-100 H. 11-35
 Carrying oil fuel in bulk
 F.P. 120°F
 Fitted for oil fuel S.M.F.P.
 above 150°F
 No later survey reported
 -1- L.M.C. 5-34
 T.S. (C.L.)

Date of Casualty
 Précis of particulars of Casualty This vessel is reported to
 to have been sunk by aircraft at Valencia during the
 Spanish hostilities. The report that she has now
 been refloated has been confirmed by cablegram from
 Valencia.

SOURCE OF INFORMATION.

CAMPRODON. — London, July 12. —
 Information received, dated June 30,
 states: Spanish tank steamer Campro-
 don was sunk by aircraft at Valencia
 during the Spanish hostilities.

L.L. 13/7/39

CAMPRODON. — Valencia, July 21. — The
 Spanish steamer Camprodon, which was
 sunk in the harbour during the Civil
 War, has been refloated. — British United
 Press.

L.L. 24/7/39

US Bul 12/39
 No 1 etc

Suggested Record Sunk by aircraft Refloated
 Date of Committee TUE 1 AUG 1939
 Committee's Minute Sunk by aircraft - Refloated