

# LLOYD'S REGISTER OF SHIPPING

OFICINA PRINCIPAL: FENCHURCH STREET, 71. LONDRES, E. C. 3.

Calle Luis Taboada, 21, 2.º centro, Vigo

Telegramas: Register, Vigo

Teléfono 16448

RECEIVED

5 - DEC 1960

30th November, 1960.

Dear Sir,

And d. ~~XXXXXXXXXX~~

"HABANA"

I have to acknowledge receipt of your cablegram reading as follows, the contents of which have been conveyed to the owner's superintendent, who has also been advised that the withdrawal of the tailshafts is not necessary at this time.

You might please confirm that the double bottom and peak tanks have in fact been previously tested.

"HABANA AT REQUEST MADRID OFFICE WOULD ADVISE  
"YOU ES TO BE COMPLETED BY MARCH SIXTYONE EXAMINE  
ALL ITEMS EXCEPT BOTH MAIN CONDENSERS INTERMEDIATE  
SHAFTS SEA CONNECTIONS STOP SUTKEY ALL BOILERS STOP  
REGARDS HULL ALL ITEMS OUTSTANDING EXCEPT EXAMINATION  
ANCHORS CHAIN LOCKER CABLE EXAMINATION TESTING OF  
PEAK TANKS DOUBLE BOTTOM TANKS= COMMITTEE"

Yours faithfully,

For the Surveyors.

The Secretary,  
LONDON.



© 2021

Lloyd's Register  
Foundation

010461-010465-0084



SD  
SR ER  
CLASSIFICATION

H. *[initials]*



© 2021

Lloyd's Register  
Foundation

2 - DEC 1990 1057 NOVEMBER 1990

LLOYD'S REGISTER OF SHIPPING