

COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegrams: Committee, London, Telex
Telex No.: 24305

Telephone: ROYal 9166

20th October, 1959.

Dear Sir,

Steamer "SANTI"

I refer to Galveston report No. 6669 and shall be glad if you will ascertain from the Galveston Surveyor and let me know whether he has any further comments to make concerning the condition of this ship's boilers.

I would explain that both boilers were cleaned at Galveston in May, 1959, when considerable sediment, mud and scale was found. Both boilers were again cleaned at Cadiz in July, 1959, and the port boiler was found covered internally in the water space with oil, the starboard boiler was found clean and in good condition at that time. The boilers were again cleaned at Galveston in August and repairs carried out.

I now await your news as to whether the Surveyor has any information or comments to make.

Yours faithfully,

Deputy Clerk to the
Classification Committee.

The Secretary,
NEW YORK.



© 2021

Lloyd's Register
Foundation

010478-010483-0016