

The class is subject to approved gas-proof electric lights being fitted in the main Pump room and bridge space at the earliest opportunity.

4E

by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor 24 AUG 1959

P'S NAME SANTI

REPORT

Cdz

No.

2851

MBS due 10.59, partly held now.

Some repairs effected to the port and centre furnaces of the port boiler and the Surveyor recommends that the class be made subject to these furnaces being re-examined before the end of November, 1959 (4 months' limit).

IT IS SUBMITTED this vessel is eligible to remain as classed, with fresh record of MBS 7.59 when the survey has been completed subject as recommended and as above.

To complete the MBS: The safety valves of both boilers to be adjusted under steam, and the oil fuel installation to be examined under working conditions.

*CN*



24.8.59



© 2021

Lloyd's Register  
Foundation

010478-010483-0024