

Received from Chief Ship Surveyor

N 1957

SHIP'S NAME

"DELUNGRA"

REPORT

Mel. No. 14813.

Outstanding Conditions of Class:

Subject to stern plating, etc. being examined and dealt with as necessary and to permanent repairs to indented 'G' strake plating, etc. (s.s.f.), indented shell plate F.2 (p.s.f.) also bulwark plating, etc. abreast Nos. 1 & 2 hatchways (s.s.) by next Special Survey.

ACTION is DEFERRED for Special Survey by 7,57.

Endorsement of Class (B) (As before ~~on 11.11.57~~)

Structure of Present Survey: (Afloat ~~and in dry dock~~)

Deferred damage repairs.

Recommendation:

SUBJECT as above, and to indented fore-castle head side plating (s.s.) being dealt with as found necessary at the next drydocking.

As Now. Subject.

ENDORSEMENT OF CLASS (B).

Indents in 'J' strake plating (s.s.f.).



© 2021

Lloyd's Register  
Foundation