

4E

ed by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

P'S NAME

"MIL 50"

REPORT

Os1.

No. 7220.

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

of Survey REPAIRS TO ENGINES AND-BOILERS DUE TO DAMAGE THROUGH encountering
ice.

Vessel placed on floating dock and sea connections and propeller examined. One propeller blade faired.

IT IS SUBMITTED that this vessel is eligible to remain as classed.



© 2021

30.3.53.Lloyd's Register
Foundation

010445-016501-020