

they should state if this is so.

ONE: 36873 (2 LINES).

3 - JUL 1944

WOKINGHAM

Lloyd's Register of Shipping,

Ocean Chambers, Lowgate,

Hull, 30th June, 1944.

Dear Sir,

With reference to your Classing Letter of the 23rd instant respecting the "EMPIRE ALDERNEY", our Report No.52469, we beg to state that the riveting in the seams of the shell plating in way of the oil tanks is as required by the Rules, and not as stated, and it is regretted that a clerical error was made in our Report.

The equipment number of this vessel is 4480 and the rudder head is fitted with a horizontal coupling as approved. The thickness of the forecastle deck plating is .26"

We are, Dear Sir,
Yours faithfully,
The Surveyors,
Per: *Renwick*

The Secretary,
WOKINGHAM.

Hull Rpt (as above) 14/6

010495-010501-0230

M.
J.C.B.

H
R.S.

13 JUL 1944

Noted
for Mr. Barlett to note

R

©2021

Lloyd's Register
Foundation