

COPY

Lloyd's Register of Shipping.

(UNITED WITH THE BRITISH CORPORATION REGISTER)

No. 2592



*is repair
service for
future e
could*

Port YOKOHAMA
 SS/MS "MATADOR"
 This Certificate 10th May, 1958
 Accompanies YOKOHAMA
 REPORT No. 2592
 Dated 10/5/58

This is to Certify that I have
 Surveyed the S.S. "MATADOR" 7310 tons gross of Panama, whilst
 lying afloat at Tokyo buoys on 8th May, 1958 and subsequently
 on account of damage stated to have been caused by heavy weather
 whilst on passage from Osaka to Tokyo, during May 1958
 and that I have transmitted to the Committee of Lloyd's
 Register of Shipping, London, a Report, stating that all repairs
 recommended by me have been completed to my satisfaction, and
 that I have Recommended that she be continued as classed
 without fresh record of docking, subject to all conditions
 attached being dealt with as previously recommended

being fit to carry her usual cargoes.

Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:-
 "While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly
 executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances
 whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any
 entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its
 Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

(CERT. B.) 9.57. K68

Lloyd's Register
 Foundation
 010445-01054-0281