

S: „LLOYDREG“, ROTTERDAM

TELEPHONE No. 25355 (2 lines)

ations to be addressed to
SURVEYORS

Lloyd's Register of Shipping,

united with THE BRITISH CORPORATION REGISTER.

Westersingel 106, P.O. Box 701, Rotterdam, 20th May, 1953.

RECEIVED

22 MAY 1953

S)
Dear Sir,

m.s. "MENCKARA"

first entry report No. 36309 .

Drawings of forepeak and engine foundation, mentioned in report, are not enclosed. They will be forwarded later.

Particulars of spare bower anchor are not given in the report as, by mistake, we did not receive the certificate. This matter will however be cleared up soon, and particulars will be sent immediately.

Yours faithfully,

Cont
The Secretary,
LONDON.



© 2021

Kranjcar

Lloyd's Register
Foundation

010509-010518-0360

CLASSIFICATION

H Kll

LONDON.
The Secretary,

Yours faithfully,

up soon and particulars will be sent immediately.
the certificate. This matter will however be cleared
Given in the report as, perhaps, we did not receive
particulars of spare power engine and not
mentioned in report, are not enclosed. They will be
Drawings of forepeak and engine foundation,
This entry report No. 30300

© 2021

Lloyd's Register
Foundation

Warrington 100, P.O. Box 101, Warrington, 30th May, 1893.

Warrington 100, P.O. Box 101, Warrington, 30th May, 1893.
Lloyd's Register

TELEPHONE NO. 32322 (3 lines)

MADE IN ENGLAND