

Message taken by Eng. Plaus

The following telephone message was received today from Mr. Samuelson, Oslo, with reference to the s.s. "MODAL":-

Cracks in screwshaft machined out "to be examined dry docking, 1962".

Lloyds letter Head Quarters 30-6-61.

"Propeller to be backed off for examination".

Ship to be sold.

New Owners are to class ship with ABS hence present Owner wishes to delete the above passage, he agrees to all the other items in letter.

The conversion is at the "Lubeck Yards".

Wishes to speak to Mr. ~~Macaffee~~ *McCaffee*

Telex Oslo 1206 ALMARINE.

Telephone 423820

Q
3.7.61.



© 2021

Lloyd's Register
Foundation

010519-010525-0070