

LLOYD'S REGISTER OF SHIPPING

ALTERATIONS TO CONDITIONS OF ASSIGNMENT OF LOADLINES

Ship's Name S/S "HOLSTEIN"

Official No. 161403

Port of Registry PANAMA


This ship has been under survey at the Port of Santos (Brazil)

on the 11th June, 1959 and subsequently and the following alterations to the conditions of assignment of loadlines have now been ~~referred~~/found:—

PARTICULARS OF CLOSING APPLIANCESPoop bulkhead - riveted plates of a permanent nature.—Bridge after bulkhead - bolted plates of a permanent nature.—

A copy of this report has been issued to the Owner's Representative to be attached to the C11 report.—

Noted
air.
30-6-59



(Charles A. Davies)

Surveyor to Lloyd's Register of Shipping

A copy of this Report has been placed on board.

5m, 8, 50. T.



© 2021

Lloyd's Register
Foundation

010537-010544-0244