

M/M. 10543

LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

FOUNDED 1760

RE-CONSTITUTED 1834

Certificate of Class

Steel Screw Motorship "KAREN MAERSK"
 Official Number - Port of Registry Copenhagen
 Owners A/S D/S Svendborg & D/S af 1912 A/S (A.P. Möller, Copenhagen, Manager).
 Builders, and where and when built Erisbergs Mek Verkstads A/B, Gothenburg, November, 1952.

REGISTERED PARTICULARS

Length	531.6	feet	Tonnage, Gross	11755.99
Breadth	69.8	feet	Ditto under Deck	10556.01
Depth	36.9	feet	Ditto Net	6851.64

This is to Certify that this Ship has been built under the Special Survey of the Surveyors to this Society, and was reported to be, on the 27th November, 1952 in a fit and efficient condition as is prescribed by the Society's Rules for the safe carriage of dry and perishable or other approved Cargoes, and has been **CLASSED** and entered in the REGISTER BOOK of this Society, with the Character **⌘100A1** Carrying Petroleum in Bulk.

subject to Periodical Surveys as required by the Rules.


Electrically Welded.


Longitudinal Framing.

The approved minimum freeboards from the deck line are as follows:—

Tropical	2535	feet	mm	inches	(T).	Winter	}	3055	feet	mm	inches	(WNA).
Summer	2730	feet	mm	inches	(S).	North Atlantic						
Winter	2925	feet	mm	inches	(W).	Allowance for fresh water for all freeboards	}	205	mm	inches		

Witness my hand,


 pro Secretary.



 Deputy Chairman.

71, Fenchurch Street, London E.C.3. 9th January, 1953.

N.B.—If the ship herein named proceed to sea with a less freeboard than that approved by the Committee, or if the freeboard marks be obliterated or placed higher than the correct position, the class will be liable to be forfeited.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, to which Owners are referred, and which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."



Lloyd's Register
 Foundation

010537-010544-0318