

COPY

LLOYD'S REGISTER OF SHIPPING



Port HONG KONG.

Date 27th May, 1961.

This is to Certify *that I have*

*surveyed the M.S. "PIENINY", 8272 gross tons, of Gdynia, afloat
and in dry dock at this Port, for Docking, Examination of
Cargo Tanks and Damage Repairs, - - - - -*

*and that I will transmit to the Committee of Lloyd's Register of
Shipping, London, a Report, stating that all repairs recommended by
me have been completed to my satisfaction, also that I will
Recommend that she be retained as classed with fresh record
of D.S. 5,61, subject to Nos.2, 3 & 4 centre tanks not being
used for dissimilar cargoes until thwartship bulkheads of
No.3 tank repaired, to port bower anchor being replaced by
an approved anchor to Rule weight and test and to screwshaft
and donkey boiler being examined not later than the end of
August, 1961.*

(Signed) James A. Anderson.

Surveyor to Lloyd's Register.

KEY TO ABBREVIATIONS


AS Annual Survey
BiS Biennial Survey
DS Docking Survey
NS Cargo Battens not fitted (No Sparring)

SS Hull Special Survey
SS(Dr) Hull Special Survey (Drilling)
SS(M) Hull Special Survey (Modified)
SS(P) Hull Special Survey (Progressive)

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that :—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any accuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

Cert. B) 30m,9,59 (MADE AND PRINTED IN ENGLAND.)



© 2021

Lloyd's Register
Foundation

010 545 - 010 553 - 0123