

COPY

LLOYD'S REGISTER OF SHIPPING



Port HONG KONG.

1st March, 1960.

This is to Certify that I have

Part & Donkey Boilers
surveyed the Machinery of the M.S. "PIEWINY", 8272 tons
gross, of Gdynia, whilst in dry dock and afloat at this Port,

and that I will transmit to the Committee of Lloyd's Register of
Shipping, London, a Report stating that all recommendations made by
me in connection therewith have been carried out to my satisfaction; also

that I will Recommend that in the case of this Vessel the following
Survey Records be made in the Supplement to the Register Book

D.B.S. 2,60, now, and C.S. (with date) when the survey has
been completed,

and that her Machinery Classification Record be continued in the Book.

Part now examined:

(M.S. Items only)

- M.S. Nos. 4 & 5 cylinders, pistons, rods, valves & gears.**
- M.S. Nos. 4 & 5 centre top and bottom ends, guides and bearings.**
- Starboard Generator Engine (No.2) (with compressor) in its**
entirety.
- Upper O.P. Unit Pump.**
- Fresh Water Cooler (Tested).**
- Sea Cocks and Valves.**

(Signed) J. Moay.

Engineer Surveyor to Lloyd's Register.

KEY TO ABBREVIATIONS

ABS	Auxiliary Boiler Survey	SGS	Steam Generator Survey
CS	Continuous Survey of Engines	SPS	Steampipe Survey
DBS	Donkey Boiler Survey	TS	Tailshaft Survey
ES	Engine Special Survey	TS(CL)	Tailshaft Survey—Continuous Liner
MBS	Main Boiler Survey	TSN	Tailshaft renewed
MES	Modified Survey of Oil Engines	TS(OG)	Tailshaft Survey—Oil Gland
OF	Fitted for oil fuel (date) FP above 150°F.		

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of its Committees is under any circumstance whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."



010 545-010 553-0126

