

2- MAR 1962

SHIP'S NAME "L E N D A V A" REPORT R o E No. 53151

EA

Outstanding Conditions of Class:

SUBJECT to poop deck guard rails and sheerstrake plating in way (s.s.a) being specially examined and dealt with as necessary next drydocking and to forward hatch coaming of No.2 port side wing tank with cover etc. being specially examined and dealt with as necessary prior to loading cargo oil.

S.R.L. Appendix. (As before or None)Nature of Present Survey: (Afloat ~~and in dry dock~~)

Permanent repairs to part deferred items as above.

Recommendation:

SUBMITTED the ship is eligible to remain as classed, subject to poop deck guard rails and sheerstrake plating in way (s.s.a) being specially examined and dealt with as necessary next drydocking, without other conditions.

As Now Subject  
Without.

OFFICE NOTE.

Deck reinforced - Rka.9,53.

Bottom shell reinforced - Ven.10,53.



© 2021

Lloyd's Register  
Foundation