

11 DEC 1954

SHIP'S NAME "BAKAR" REPORT Rka. No. 138

GB

Outstanding Conditions of Class:

Subject to indented shell plates
B.5 (p.s.) and D.5 and E.5 (s.s.) being dealt with by next Special
Survey, also to indented side shell plating (p & s) being dealt
with as necessary next drydocking.

Endorsement of Class (B) (~~As before~~ None)Nature of Present Survey: (Afloat and in dry dock)

Docking: Damage (contact) involving bottom and side shell plating
(p & s).

Recommendation:

SUBMITTED record of docking 11,54 be assigned,
subject to permanent repairs to indented bottom
and side shell plating, etc. (p & s) by next
Special Survey.

11,54 Rka. Subject
Amended.



© 2021

Lloyd's Register
Foundation