

Fastenings good

Has Screwshaft Tubeshaft been drawn? no

Date of Examination -

Has Shaft been

Has Shaft now fitted been previously used?

Man sea inlet valve being renewed on completion
present voyage.

4E

subject to

by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

13 SEP 1961

S NAME 85. 'SAN ROCCO'

REPORT

Rotterdam

No. 52/30.

MBS. due 6/61, partly held 4/61, now advanced.

ES due 3/61, partly held 5/61, now advanced. (Postponement of)

ES to 3/62, approved 12/4/61 provided satisfactory G.E. held.

G.E. held partly 4/61, now completed.

Docking, Repairs.

SRH. The above item dealt with and to be deleted.

man circulation pump renewed.

It is submitted that the
vessel WILL BE eligible
for the record MBS 4/61, ES (with date)
when the survey has been
completed, without condition.

To complete MBS:- adjust all boiler safety-valves, examine oil burning
system & remote controls.

To complete ES:- See Form 10 E attached.
It is further submitted that postponement
of ES until 3/62 merits approval.

13/9/61

010605-010614-0220