

IX 2500.10.38.

1

Todd-California Shipbuilding Corporation, Richmond Cal. Yard No. 17

How Capitaine Lammertine

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME s.s. OCEAN VETERAN Report Richmond, Cal. No. 17

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey First Entry When due

This is a sister vessel to the "OCEAN VANGUARD" etc.

The tonnage Opening has been closed and the draught is about 18 $\frac{1}{2}$ " in excess of that corresponding to the freeboard which could be assigned as a C.S.S. vessel.

#100AL "With freeboard"

2 Dks "Electrically welded"

Cell DB 368' 1308t, DTA 20' 734t, FPT 124t, APT 166t

FK, 7BH (Coll to W dk, 6 to 2nd dk), 6 divisional W.T. BHs in 'tween dks., pt. Cem., Lloyd's A & CP


O.L. 441.5'

E.S.D.

a†

The class is assigned and maintained upon the understanding that the equipment will be made to accord with the requirements of the Rules when the present state of emergency has passed.

Insert in S.R.L.:- (A bower anchor and 45 fathoms chain cable to be supplied).



© 2021

Lloyd's Register
Foundation

010605-010614-0222

7.8.42

"	"	"	Through Plate or Intercostal Plate...}	---	
"	"	"	Foundation Plate on Floors	---	

Spacing.....

Third Deck, amidships, Angle, [or [.....

6

e 6

8x3 $\frac{1}{2}$

43.5

one

68 x

Welde
tank
brack

12 x

cont

15 x

d con

85.5

60 x

7

ev.

8

7

ev.