

Ceiling in Holds, thickness and material 65 mm Soft Wood

Cargo Battens, thickness, material

(Req. la.)

(Received at London Office ..... 19 .....) )

No. \_\_\_\_\_ Place YOKOHAMA Date ..... 19 .....

We request that the Committee of Lloyd's Register will instruct the Society's Surveyors to Specially Survey during Construction the Hull, Engines and Boilers of the Vessel No. 673 building by Messrs. Uruga Dock Co., Ltd. for Messrs. Nitto Shosen Co., Ltd.

of 6,600 Gross Tons. Length 421'-1 1/2", Breadth 58'-4 3/4", Depth 34'-1 1/2" intended to be Classed + 100A1 & + L.M.C.

We undertake to arrange for every facility to be given to the Surveyors to carry out the duty in question, and we agree to pay the fees for the Surveyors' services, in addition to the actual travelling and other expenses incurred by the Surveyors in connection therewith.

This request is made upon the terms of the Rules and Regulations of Lloyd's Register of Shipping, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

*Authorisation from set  
yba (via kbe) 29.12.54  
kwd*

Engine Makers Uruga Tamashima Diesel Co., Ltd.

Boiler Makers (Donkey) Uruga Dock Co., Ltd.

To the Secretary,  
Lloyd's Register of Shipping,  
71, Fenchurch Street, London, Signature R. Nagashima  
for KIYOTAMI TOYOFUKU  
GENERAL MANAGER  
URUGA SHIPBUILDING YARD,  
THE URUGA DOCK CO., LTD.

NOTE.—To avoid misunderstanding, orders for materials requiring to be tested should be marked as follows:—

"Inspection and Testing by Lloyd's Register Surveyors to the Society's requirements."

Special Survey Fee..... £ : : 0/10

Received by me,

We are

010615-010623-0127

Lloyd's Register  
Foundation

part of cl