

Donkey 33 33 33 33
010615-010623-0245

23 DEC 1948

by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

EL'S NAME "SHEAF MEAD"

REPORT

Bel. 14615

Nwc. No. 105635

marks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Survey ~~COMPLETION OF SPECIAL SURVEY OF ENGINES AND BOILERS FOR S.S. No.~~

This Survey, due 6.48 now held
partly

completed, and the following repairs carried out (due to -----):—



© 2021

Lloyd's Register
Foundation

It is submitted the vessel is eligible to remain as classed, with
notation of BS 9.48, as recommended.

3. 12. 48.

sight holes, doors, mountings and guesings, and repairs to
the hull, and the engine and boiler.