



LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

2, Laidlaw Building, Battery Road,

(P.O. Box 480), Singapore

WPW/PK

Telegrams: Surveyor

10th November, 1952.

Telephone No 22861

Reference

Classn(S)

RECEIVED

17 NOV 1952

Ans.....

Dear Sir,

MOTORSHIP "BUNGA"

We have for acknowledgment your letter dated 31st October, 1952 and in reply wish to state that the approved plans were despatched under separate cover by surface mail on the 10th October, 1952. This fact was recorded on our Ltr.5 dated 9th October, 1952.

With regard to the General Declaration it is confirmed that the ship was built in accordance with Section 27, "Instructions to Surveyors" Part 2a, 1950, which reads as follows:-

"This ship has been built under Special Survey in conformity with the Society's Rules and Regulations and Secretary's letters. The scantlings and arrangements of the ship are as given in the report and as shown and amended on the approved plans now forwarded. All modifications or additions to the original approved arrangements made during construction have been indicated on the plans and have been approved as being in accordance with, or by standards equivalent to, the Rule requirements. The plans of midship section and profile and decks showing the ship as built, now forwarded herewith, have been checked with the approved arrangements and found in order."

The error is very much regretted.

Yours faithfully,

W. P. Watson

FOR THE SURVEYORS.



Lloyd's Register
Foundation

The Secretary,
LONDON.

010624 - 010630 - 0019

FE16-10.

