

REGULAR SAILINGS BETWEEN  
LONDON, CONTINENTAL PORTS, HAMBURG  
AND LENINGRAD, BLACK SEA PORTS.

**ANGLO-SOVIET SHIPPING Co.**  
**LIMITED.**  
(LATE ARCOS STEAMSHIP CO. LTD.)

MANAGING DIRECTOR : I. E. LEONIDOFF, RUSSIAN  
DIRECTORS : M. SHEFFER, „  
LOUIS SEGAL. BRITISH

'INLAND TELEGRAMS'  
'SOVFLÖT. BUSH. LONDON'

TELEPHONE :  
 TEMPLE BAR 5411.  
 INLAND TELEGRAMS :  
 SOVFLOT, ESTRAND, LONDON.  
 CABLEGRAMS :  
 SOVFLOT, LONDON.  
 CABLEGRAMS—CHARTERING DEPT.  
 ARCOFRACHT, LONDON.

**CODES :**  
A.B.C. 5TH EDITION.  
SCOTT'S WATKINS.  
B.O.E. CODE.

BUSH HOUSE, ALDWYCH.

LONDON, W.C.2.

13800

Messrs Lloyd's Register of Shipping  
71 Fenchurch Street,  
LONDON, E.C. 3.

3. **LLOYD'S REGISTER**  
RECEIVED  
29 JUN 1931

26th June 1931

Dear Sirs,

Ansd.  
**LONDON**

S. S. "PRAVDA"

In reply to your letter of the 15th inst., we beg to inform you that the Owners of the above steamer have decided not to retain the class of your classification Society, and the vessel will now be in the class of Register of U.S.S.R. only.

Your account for the surveys at LIVERPOOL during the repairs has been passed for payment.

Yours faithfully,  
ANGLO-SOVIET SHIPPING CO. LTD.

(S. JOUKOFF)

(N. VOLKOFF)

© 2020

Lloyd's Register  
- 010639-0187

010631-010639-0187



Referred to *the Chief Surveyors*  
*Mr. S. A. Hill.*

*AS*  
29 JUN 1931  
*Also for Mr. Aicaph  
+ Mr. Carey to ask*

LONDON, W.C.5.

BUSH HOUSE, ALDOWAY.

1931

© 2020

Lloyd's Register

Foundation

If so, is the Report sent now, or when will it be sent?

REPAIRS,

In damage as  
offered hi

SUMMARY OF

Renewed  
Removed  
Paired or  
PRESENT CON

Decks

Caulking of Deck

Coamings

Beams & Fasten

Outside Plating

Breasthooks

Transoms

Frames

Reverse Frames

Longitudinals

Transverses

Floors

Keelsons

Stringers

Inner Bottom Pl

General

this sur  
survey.

Survey Fee (per

Special Damage  
(per sec.

Travelling Expe

Second Surveyor

Committ