



Please address
further communications
on this subject to
THE PRINCIPAL SURVEYOR

Lloyd's Register of Shipping

UNITED WITH THE BRITISH CORPORATION REGISTER

751 Victoria Square,

Montreal 1.

15th May, 1951

RECEIVED

18 MAY 1951

Ansd.....

The Secretary
LONDON

Dear Sir;-

S/S "ROCKSIDE"

This will acknowledge receipt of your letter of the 7th instant, regarding the above Vessel.

The Owners, as yet, have no record of the H.P. Piston Valve Liner having been examined in Bombay.

However, with regard to the Boiler Survey the Owners' Representative states that the Vessel is due in Charleston towards the end of this month when the Boiler Survey will be carried out. Should it not be possible to complete the survey at that time, it will be completed during the Vessel's stay at Cuban Ports.

The Owners' Representative also stated that opportunity will be taken to examine the H.P. Piston Valve Liner during the Vessel's stay at Charleston.

Yours very truly,

Principal Surveyor for Canada

ARR:FC

c.c. The Principal Surveyor, New York



© 2021

Lloyd's Register
Foundation

010720-010726-0021

Quigley to JTF-PMW/AFM
GROUP 2 GROUP 1 127

© 2021
Lloyd's Register
Foundation

1. JTF-PMW/AFM

1. JTF-PMW/AFM

1. JTF-PMW/AFM

1. JTF-PMW/AFM



1. JTF-PMW/AFM

1. JTF-PMW/AFM

1. JTF-PMW/AFM

1. JTF-PMW/AFM

1. JTF-PMW/AFM

1. JTF-PMW/AFM

1. JTF-PMW/AFM

1. JTF-PMW/AFM

22/5/15

CLASSIFICATION
The
is submitted action re
defence.

E.