

Rpt. 8.

DISCLOSED

SECTION.

(Received at London Office

London

No. 117430A

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 19... When handed in at Local Office 19... Port of

No. in Reg. Book. Survey held at Date, First Survey Last Survey 10 19 49

on the Wood, Iron or Steel SS. CILURNUM Master

TONNAGE:-

GROSS 3017

UNDER DK. 3844

NET 1845

Built at Middlebrough

By whom Sir Raylton Dixon & Co. Ltd. When 1919

Owners A. Menchaca & Cia

Port belonging to Bilbao

Owners' Address

(if not already recorded in Appendix to Register Book).

Surveyed Afloat or in Dry Dock?

Name of Dock

Destined Voyage

WB=CellDBorDBa

feet; uE&B

feet; f

feet; f

total capacity

tons. FPT

tons; APT

tons; MT

feet

tons.

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

N.B.—All alterations in the existing records should be underlined.
If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 10515

Port

Bbs

(Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

CHARACTER.	Year Assigned	Year Expired	Machinery and Boiler Surveys (including date of N.B., if any).
BS*	1948	1949	MBS* 1.45
SS Bbs 2-4 Nov 1-45			BLS 4.49
Annual Survey 2.48			msp 12.39
			TS 10.42 CL

Society's Freeboard (if assigned) as painted on Ship and now verified ft. ins.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined? Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

DISCLOSED SECTION

SUMMARY OF DAMAGE REPAIRS :-	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items :-
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

PRESENT CONDITION OF THE

Decks	State if Tanks have been examined inside	Dblg. Plates under Sounding Pipes	Copper, or Y.M. of Wood Vessels
Caulking of Decks	State if Tanks now tested	Engine Room Skylights	(State if on Felt.)
Waterways	Bulkheads	Coal Bunkers, Open'gs, Lids, &c.	When put on, Month Year
Coamings	Ceiling	Scuppers	Boats
Beams & Fastenings	Cement or Asphalt	Cargo Hatchways	Masts, Yards, &c.
Outside Plating	(State which.)	Hatches	Condition, how ascertained
Caulking of ditto	Rudder	Planking of Wood Vessels	(State if wedges removed)
Rivets	Steering gear and its connections	Caulking ditto	Sails
Breasthooks & Crutches	Windlass	Treerails ditto	Equipment letter
Transoms	Have Pumps now been examined and found efficient?	Breasthooks & Stemson ditto	Anchors, No. o
Frames	Have Sluice Valves now been examined and found efficient?	Transoms, Pointers, & Crutches ditto	Cables (State if now ranged)
Reverse Frames	Have Watertight Doors now been examined and found efficient?	Timbers of Frame at openings ditto	" length size
Floors	Have Ventilators and their Coamings been examined and found efficient?	Ditto ditto at other places ditto	" Rule length size
Keelsons		Stringers, Clamps & Shells ditto	Hawser & Warps
Stringers		Salting (State if examined.) ditto	Standing & Running Rigging
Inner Bottom Plating			

General Observations, Opinion as to Class, Recommendation, &c.:-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,15," or "to remain as classed and to have record of survey, 1,15, and the notations of ss No. 1-15 and ptND15, &c."

Survey Fee (per Section 25) £

Special Damage or Repair Fee (if any) (per Sec. 26) £

Travelling Expenses (if chargeable) £

Second Surveyor's Fee (if any) £

Fees applied for,

19

Received by me,

19

Surveyor to Lloyd's Register of Shipping.

Committee's Minute

Character Assigned

Write Bbs

With draw BC class

a misent disclosed BS* (in Cl. 3)

Special General Committee
Thursday 13th October 1949
Classing Committee
decided on 13th Oct 1949

In Certificate required? If so, to be sent to