

DCW

BRITISH CORPORATION

16 AUG 1949

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME CILURNUM REPORT Bbo. No. 10515

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/42.)

This ship is classed BS *.

A SPECIAL SURVEY TYPE 4 and Annual (Classification) Survey became due 1.49.

The BILBAO Surveyors report (5.49) ship examined afloat on account of damage sustained through contact with fishing vessel whilst lying alongside at Availles, and repairs effected to slightly indented and fractured sheerstrake plate No. 3 (p.s.)

IT IS SUBMITTED ACTION be DEFERRED for Special Survey.

15
8
149



© 2021

Lloyd's Register
Foundation

010720-010726-0231