

Do. of excess of Hatchway 13.11  
Do. above Crown of }  
Engine Room .. } 214.08

Longitudinal Number.....

4954

Owners The E

TELEPHONE No. 610.



# Lloyd's Register of Shipping.

Ocean Chambers, Lowgate,

LLOYDS REGISTER.  
LONDON.

REC'D AUG 3 1915  
ANSD

Hull, 31st. July 1915.

Reference

Dear Sir,

In reply to the question in the classing letter of 30th. inst.,  
regarding the spacing of stiffeners on collision bulkhead on the S.S. "AISNE"  
I beg to state that these stiffeners are spaced 24" apart.

I am, Dear Sir,

Yours faithfully,

M. Blackwood

The Secretary,

LONDON.



© 2021

Lloyd's Register  
Foundation

010766-010776-0104

on the collision bulkhead and spaced  
24" apart but the Drawings should



Referred to the Chief Ship Surveyor.

Also for Mr. S. A. Hill to note.

7g WND  
4.8 18

RECEIVED

21 JAN 1918

RECEIVED

RECEIVED  
NOV 10 1917



© 2021

Lloyd's Register  
Foundation

50.114

Received

VESSE

The

Tr

Fi

Lo

Ru

be

BEAN

Do. of acc  
Do. above  
Engrs