

1
ECW

Sent to Chief Surveyors.....

Received from Chief Surveyors.....

VESSEL'S NAME AGATE REPORT Gls. No. 75785For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR.~~

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey Docking. When due ---NOTED

Subject to 30 fathoms of chain cable being supplied at the earliest opportunity.

ENDORSEMENT OF CLASS (B)

Indents in fore-castle side plating (p & s) and in upper edge of bilge strake (p.s. amids.).

CARGO BATTENS NOT FITTED.



© 2021

Lloyd's Register
Foundation

Floor

Keelsons

Staircase

efficient? 1/10.

010777-010782-0142

Timbers of Frame at openings

AM.
16.8.50.

Cargo battens not fitted