

Received from Chief Ship Surveyor

SHIP'S NAME "ARSTERTURM" REPORT Hul. 4 MAY 1956 1052 093

CB

Outstanding Conditions of Class: NONE.

Endorsement of Class (B) (As before ~~EXXONS~~)

Nature of Present Survey: (~~Afloat and~~ in dry dock)

Docking: Damage (ice) involving rudder plating and side shell plating (s.s.).

Recommendation:

SUBMITTED record of docking 4,56 be assigned, subject to shell plates E.10 & 11, F.12 (s.s.) from aft, being examined and dealt with as necessary next Special Survey, with Endorsement (B).

4,56 Hul. Subject.


ENDORSEMENT OF CLASS (B) (AMENDED).

Indents in keel and bottom plating (p.s.) and in side shell plating (s.s.).
Rudder plating slightly indented.

IN S.R.L.

(Part "Thomas" Steel structure to be examined and reported up on annually) Last examined 9,55.

Blk (new)



© 2021

26-4-56

Lloyd's Register
Foundation

010805-010815-0238