



La correspondencia  
debe dirigirse a los  
Inspectores

# LLOYD'S REGISTER OF SHIPPING

OFICINA PRINCIPAL: FENCHURCH STREET, 71. LONDRES, E.C. 3.

Avenida del Generalísimo Franco, 2, 1.º Cádiz

Telegramas: Registro

Teléfono 14555

2nd June 1962

Classn (S)

4868 TONS  
s.s. "JUPITER" Cadiz Report N° 3287

Dear Sir,

In reply to your classing letter of the 24th May we confirm that the hatchways, water tight doors and casings etc. were examined and found satisfactory, and that the internal repairs to the shell of the satarbiard boiler were examined and remain efficient.

It is regretted that these items were not made clear in our report. The note in Italics in the Appendix to the SRL, regarding the shell of the starboard boiler should be left unchanged.

The remarks regarding a definite limit for recommendations to be made on both the certificates and in the reports are noted.

We have now received a letter from the Bilbao Surveyors in which they state that the Owners are now requesting a postponement of the Special Survey of this vessel until April 1963. As the original request was for one round voyage to the United States, and this was agreed by the Committee, as per classing letter to Bilbao Surveyors dated 24th May 1962, we should be glad to have your further instructions .

yours faithfully

*John Douglas*

John Douglas  
for the Surveyors

The Secretary  
London



© 2021

Lloyd's Register  
Foundation

019816-010823-0016



pp

REPORTS  
FREEBOARD

pm

What  
is



© 2021

Lloyd's Register  
Foundation