

24th May, 1962.

CADIZ

3281 "ALBUERA" - As recommended.

Please confirm that the boiler securing arrangements were examined and found good, and that the safety valves of both boilers and the exhaust gas heated economiser were adjusted. In future you should state clearly in your reports the boilers on which the safety valves have been set, and report the items in the proper space provided in the Rpt.9.

3287 "JUPITER" - As recommended, the Committee having agreed to the Special Survey being postponed to enable the ship to make one return voyage to the United States.

It is concluded that the hatchways etc. W.T. doors and casings were examined, but confirmation of this is desired.

Please also confirm that the internal repairs to the shell of the starboard boiler in way of the safety valve opening were examined and found good.

In future you should recommend a definite limit for your recommendations to be carried out in both your certificate and reports.



© 2021

Lloyd's Register
Foundation

010816-010823-0018