

COPY.

Lloyd's Register of Shipping.



Port Vancouver, B. C.

May 6th, 1932.

This is to Certify that

S. F. BOOMER

the undersigned Surveyor to this Society did at the request of the Owner's Representative, survey the Twin Screw Steamer "PRINCESS JOAN" 5251 tons gross register of Victoria, Official Number 156465, for

ANNUAL LOAD LINE INSPECTION.

On the 2nd. day of May, 1932, while the vessel was lying in dry dock at Esquimalt, B. C., the undersigned upon examination, found:—

that the (a) protection of openings, (b) guard rails, (c) Freeing ports, (d) means of access to crew's quarters have been maintained in an effective condition, and that, in my opinion, there have been no alterations made to the hull or superstructure which would affect the calculations determining the position of the load lines.

S. F. Boomer

SURVEYOR TO LLOYD'S REGISTER OF SHIPPING

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Committee nor the Society are under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default, or negligence of the Surveyors, or other Officers or Agents of the Society."