

Received from Chief Ship Surveyor .....

SHIP'S NAME "BIDDY" REPORT Hul. No. 60512

Outstanding Conditions of Class: NONE.

Endorsement of Class (B) (~~As before~~ or None)

Nature of Present Survey: (Afloat and in dry dock)

Docking: Damage to rudder (cause unknown).

Recommendation:

SUBMITTED record of docking 8,54 be assigned,  
with Endorsement (B).

8,54 Hul.

ENDORSEMENT OF CLASS (B).

Upper end of rudder stock slightly twisted.

IT IS FURTHER SUBMITTED the Surveyors be advised it is  
concluded that the upper end of rudder stock remains twisted,  
but confirmation is desired, as it is considered this should  
become an Endorsement of Class (B) item.

*See letter  
dated 20-9-54*

*11/9*  
Lloyd's Register  
Foundation