

COPY.

----- Mr. Engeldow c/o Lisbon Surveyors.

3.6.25.

M.

AMARANTE

AZZIF - doubling plate
EJLAS - required

AWLUN - bridge deck
EGZEV - may be

EFKID - fitted to
ECVUG - any

continuous strake

AXUTE - plating
EHJUP - on

EKENY - this
AWIMU - deck

EBTIW - stop
EFZIS - if

ECUKS - after
AKAHD - examination of ballast tanks

EGNTO - internally
EGJOJ - in way of

EFJUF - feet
AXRIW - pillars

you are satisfied

EKEDA - that
EHBUE - necessary

EKASM - strengthening
EDZON - could be

EHJIM - obtained
EDPABZ - by

EFENY - double
EKMAZ - vertical



© 2021

Lloyd's Register
Foundation

010905-010912-0220 1/2

COPY.

-2-

AVSIM - angles

attaching intercostals

EKFUW - to

AWUTY - floors

EHLDU - or

EDPAB - by

EHLLP - other

means

EKHIV - to your satisfaction

AZAWU - intercostal plates

need

EHDYL - not

EDMAX - be

carried down

EKHBI - to the

AZUXU - shell plates.



© 2021

Lloyd's Register
Foundation

0220 2/2