

COPY.

Extract from Newcastle Classing Letter of the
5th December, 1924.

-:-----:-

"TACITO". 78591..... It is concluded that the solid floors are spaced four feet apart in the boiler space and that the thickness of the tank top plating and margin plate in the boiler space is as approved, but you should state if this is so.



© 2020

Lloyd's Register
Foundation

010913-010923-0209