

TELEPHONE: SUNDERLAND 4093 (2 LINES).

Letters to be addressed to
SURVEYORS.

Lloyd's Register of Shipping,

55, Fawcett Street,

Sunderland, 18th April, 1947.



Dear Sirs,

M.V. "CYRENA".

In reply to your letter of the 16th instant, we have to advise you that the cables between the engine room and midships are clipped to 12" Rolled Steel channel sections on edge, running fore and aft and lifted 9" clear above the deck top. A similar arrangement is adopted between midships and foremast.

The cables are cleated in accordance with rule requirements.

We are, Dear Sirs,

Yours faithfully,
THE SURVEYORS,
PER:

The Surveyors,
MIDDLESBROUGH.



Lloyd's Register
Foundation

010992-011000-0013

floor or ceiling, as indicated on the approved midship section, but they should state if this is so.