

6 - MAR 1946

to Chief Surveyors.....

Received from Chief Surveyors.....

SEL'S NAME "MOYRA" REPORT Lon. No. 113464A

For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR.~~

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)


of Survey..... When due.....

The Owners state this vessel ~~is~~ is now being reconstructed to British Corporation Class.

It is accordingly submitted the class of this vessel be withdrawn from the Register Book and three dots (...) inserted in lieu, indicating withdrawal of class at the Owners' request.

Withdraw class  
Insert (...)

*[Handwritten signature]*



© 2021

25.2.46.

Lloyd's Register  
Foundation

011001-011010-0140