

DISCLOSED SECTION

Rpt. 8.

(Received at London Office)

221

London No. 113464A

REPORT OF SURVEY FOR REPAIRS, &c.

Date of writing Report 19..... When handed in at Local Office 19..... Port of

No. in Reg. Book. Survey held at Date, First Survey Last Survey 19.....

29939 on the Wood, ~~Iron~~ or Steel. S.S. "MOYRA"

TONNAGE: GROSS 1396, UNDER DK 1197, NET 759. Built at Sunderland. By whom Susan Hunter & Wigham Richards. When 1931. MONTH 5. Owners Shaw SS. Co. (Newfoundland) Ltd. Managers G. Y. Shaw. Port belonging to St. John's NFL.

Surveyed Afloat or in Dry Dock? Name of Dock. Destined Voyage.

Cell DBor DBa feet; uE & B feet; f feet. total capacity tons. FPT tons; APT tons; MT feet tons.

Only alterations in the existing records of tanks should be inserted.

N.B.—All alterations in the existing records should be underlined.

Last Report, No. 5118. Port Hlx.

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules and items remaining to complete the Surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.)

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)

Table with columns for CHARACTER, Date of last Survey, and Machinery and Boiler Surveys. Includes handwritten entries: +100 A1 with fld 9.44, +LMC 10.43 BS 9.44 TS CL 2.44.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined.

Society's Freeboard (if assigned) as painted on Ship and now verified } ft. ins.

Was a damage report made by anyone else? if so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

SUMMARY OF DAMAGE REPAIRS table with columns: Shell Plates, Frames, R. Frames, Floors and Bracket Floors, Beams, Inner Bottom Plates, Dk. Plates, Other Items. Rows: Renewed, Removed and Faired or Repaired, Faired or Repaired in place.

PRESENT CONDITION OF THE

Table with columns for Decks, Bulkheads, Engine Room Skylights, Copper, or Y.M., Caulking of Decks, Ceiling, Coal Bunkers, Openings, Covers, &c., When fitted, Month, Year, Coamings, Cement or Asphalt, Oil Bunkers, Scuppers, Boats, Beams & Fastenings, Rudder, Cargo Hatchways, Masts, Yards, &c., Outside Plating, Steering gear and its connections, Hatches, Condition, how ascertained, Frames, Have pumps been examined and found efficient?, Planking, Equipment letter, Reverse Frames, Have Sluice Valves been examined and found efficient?, Caulking, Anchors, No. of, Longitudinals, Have Watertight Doors been examined and found efficient?, Treenails, Cables (State if now ranged), Transverses, Have Watertight Doors been examined and found efficient?, Breasthooks & Stemson, length, mean diamr., Floors, Have Ventilators and their Coamings been examined and found efficient?, Transoms, Pointers & Crutches, Rule length, size, Keelsons, Air and Sounding Pipes, Stringers, Doubling Plates under Sounding Pipes, Timbers of Frame at openings, Chain Locker, Inner Bottom Plating, Salting, Hawasers & Warps, Have the Tanks been examined internally?, Stringers, Clamps & Shelves, Standing and Running Rigging, Have the Tanks been tested?, Doubling Plates under Sounding Pipes, Salting, Sails.

General Observations, Opinion as to Class, Recommendation, &c. :-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."

Fees table: Survey Fee, Special Damage or Repair Fee, Travelling Expenses, Second Surveyor's Fee.

Committee's Minute

Character Assigned

FRI. 8 MAR 1946

Special General Committee Thursday, 14th March 1946 Classing Committee decision confirmed etc.

01001-01010-0141 © 2021

Surveyor to Lloyd's Register of Shipping.

Lloyd's Register Foundation

90m. 11/41.—Transfer Ink. (MADE AND PRINTED IN ENGLAND.) (The Surveyors are requested not to write on or below the space for Committee's Minute.)

Is Certificate required? If so, to be sent to